



interface: solid stress/strain continuous,
pressure change is also continuous $\delta p_j = \delta p_j^*$
dispersion relation for linear wave propagation
defined by satisfaction of the boundary conditions